

Molders of Engineered Materials

1950450006-Whiteside County
Haas + Haas, Roxite Fiberglass Div.
ILD 061047502
Compliance File

August 30, 1988



Ms. Angela Aye Tin, Manager
Tech Compliance Unit
Compliance Section
I. E. P. A.
Division of Land Pollution Control
2200 Churchill Road
P. O. Box 19276
Springfield, IL 62794-9276

Dear Ms. Tin:

In response to your letter of August 23, 1988, in which your agency found a possible non-compliance to 35 Ill. code, Part 722, Roxite Fiberglass has made the following determinations.

The small amount of material which had previously ran out of the hopper and solidified (approx. 2 to 3 gallon) and the liquid observed by the inspector from your agency, which had accumulated in the bottom of a trash barrel being dumped (1 or 2 gallons) was determined to be clean up liquids from a latex emmulsion product.

On July 15, samples of the liquids in question were sent to an outside laboratory for analysis, results of which are attached. Sample #55480 Blacktop Primer rinse water, and sample #55481, Concrete Sealer rinse water, are the only two liquid containers that are disposed of in this manner. Although #55480 being black in color and #55481 being clear to slightly white in color, both liquids tested out to be exclusively water and presented no threat to the environment, even though the observed residue was cosmetically unappealing.

To prevent recurring problems of this nature, responsible personnel have been instructed never to place clean up water into the hopper even though it has been deemed non-hazardous. The residue from the rinse water has been thoroughly cleaned up. Soil penetration appeared to be negative. Sand has been spread over the area to aid in detection and clean up of a possible recurrance.

Having analytical test now showing the liquid in question is of a non-hazardous nature, determining the source and having taken steps to

RECEIVED

AUG 3 1 1988

IEPA-DLPC

ROXITE Fiberglass 803 East 11th Street P.O. Box 830 Rock Falls, Illinois 61071-0830 Telephone: 815-625-8112 prevent future such occurrences, and having improved the physical nature surrounding the trash hopper itself, Roxite Fiberglass feels we have addressed the issues brought forth in your August 23 letter and consider ourselves in compliance pending you approval.

Jenus Willy Dennis Milby Quality Control



NET Midwest, Inc. Rockford Division 3548 35th Street Rockford, IL 61109 Tel: (815) 874-2171

Formerly: Aqualab, Inc.

ANALYTICAL REPORT

Mr. Tim Haas ROXITE FIBERGLASS P.O. Box 830 Rock Falls IL 61071 07-26-88

SAMPLE DESCRIPTION: Rinse Water Samples

Date Received: 07-18-88

55480 Blacktop Primer(Latex Emmulsion) 07-15-88

Water (Karl Fischer) 100.

55481 Concrete Sealer/Bonder(Latex Emmul) 07-15-88

Water (Karl Fischer) 100. %

55482 Concrete Cleaner (Kerosene Emmulsion 07-15-88

Water (Karl Fischer) 93. *

RECEIVED

AUG 3 1 1989

IEPA-DLPC

Ton't Gartner, Manager Rockford Division